




High Power Connectors


www.oupin.com

BusBar Clip Power Connector Screw Assembly, Solder Type


150A
9192



150A
9192




16A with Switch
9192-A




High Power Power + Signal, Solder, Press Fit


65A
9303




65A
9303




65A
9303




30A
9391




30A
9391



30A
9391




30A
9391




High Flow Power Power + Signal, Solder, Press Fit


35A/45A
9113-A




35A/45A
9114-A




35A/45A
9114-B




35A/45A
9114-A




35A/45A
9113-A




35A/45A
9114-A/B




35A/45A
9114-A/B




35A/45A
9113-A




35A/45A
9114-A




35A/45A
9113-B




20A
9113-C




20A
9114-C



150A
9113-D




150A
9114-D



2.0mm Power Press Fit

15A
9113-N



15A
9114

